

1/12




FIG. 1

[illegible]

THE UNIVERSITY OF CHICAGO

3/12




FIG. 3

4/12

TEARDOWN

SMS ORDER # 765432

ABC AIRLINES

SECTION 78-33-00

EXPLODE FAN CASE

78-33-00-2 CASE & VALVE ASSY-FAN EXIT

0078-33-00-2-1 CASE & VALVE ASSY-FAN EXIT

00078-33-00-2-10 WIDGET

212 ☐ 12345

☐ 12345-01 (EXPECTED)

☐ 12346 (PLANNED)

☐ 12350

OK

FIG. 4

10064105 .061102

5/12




FIG 5

402

404

INSPECTION

SALES ORDER # 987654 SECTION 72-52-00 HPT C/D & FINAL ASSY

Pu4074 XYZ AIRLINES

PART # 506745-01 QTY 1

CASE-TURB, ASSY OF

TECH INFO CONFIGURATION DISPOSITION STATUS

☒ EM
☐ IPC
☐ SB
☐ SPM

406

408

VIEW

400

6/12

FIG. 6a

10064105-05102

402

INCEPTION

SALES ORDER # 987654 SECTION 72-52-00
 RW4074 HPT 4D & FINAC ASSY
 KYE AIRLINES
 PART # 506745-01 QTY 1

416

TECH INFO CONFIGURATION DISPOSITION STATUS

418

7/12

410

REQUIRED MODS

725200-02-04D

FW4G-11272-141
 FW4G-11272-159

EXCHGIBLE REPLACEMENTS

QTY	TYPE	RELATION
1	R	REPLACE
1	R	REPLACE

420

FIG. 6b

10064105 061102

6/18

4022

INSPECTION			
SALES ORDER # [9874654] ▼		SECTION [72-52-00] ▼	
P4074 XYZ AIRLINES		HPT CID & FINAL ASSY	
PART # [506745-01] ▼	QTY [1] ▼		
TECH INFO / CONFIGURATION		DISPOSITION / STATUS	
<div><input checked="" type="radio"/> SERVICEABLE <input type="radio"/> REMOVE FROM SERVICE <input type="radio"/> INTERNAL REPAIR <input type="radio"/> CHANGE INTERNAL REPAIR <input type="radio"/> EXTERNAL REPAIR <input type="radio"/> HOLD</div>			
<div>Disposition</div>			

412

FIG. 6c

10064105 - 061102

9/12

402

INSPECTION

SALES ORDER # 987654 SECTION 72-52-00
HPT C/D & FINAL ASSY

PART # QTY

414

TECH INFO CONFIGURATION DISPOSITION STATUS

LID	PART #	DESCR	STATUS
72500-01-001	534071	ROTOR & ST. ASSY	○ ○ ○ ○
72500-01-160	50476	SEAL	○ ○ ○ ○
72500-01-170	507965	METER/INB PLUG	○ ○ ○ ○
72500-01-001	504877	PLATE	○ ○ ○ ○
72500-02-40	53401001	CASE-TURB ASSY	○ ○ ○ ○
72500-02-040	50475	GRANULET	○ ○ ○ ○
72500-02-160	534013	GRANULET	○ ○ ○ ○
72500-02-180	504569	SEAL	○ ○ ○ ○

422

FIG. 6d

10064105-064102


10/12

PART #: 12345-01
NAME: B WIDGET
CUST: ABC AIRLINES
306 { SERVICEABLE
310
ROUTE: KITTING, ASSY

300

FIG 7a

11/12

PART# 12345-01
NAME 8 WIDGET
CUST 8 ABC AIRLINES
306 { REMOVE FROM SVC

ROUTE 8 MAB } 310

300 ↗

FIG. 7b

10064105-061102

12/12

PART # 12345-01
NAME WIDGET
COST ABC AIRLINES
300 {REPAIR
310
ROUTE XYZ VENDOR

300 ↗

FIG. 7c